

Published date	12/12/2018
Document number	SUPAIR_2018/12/002
Page number	1 / 2



Safety info

STATUT :

LOW

MEDIUM

CRITICAL

SUBJECT : ACRO BASE harness

Lateral adjustment straps tear

Problem description :

Caution, the side backrest adjustment strap (higher one) may be damaged in the adjustment buckle.



Concerned products :

ACRO BASE harness

Indice A1 à B4



Facts/ Ascertainment :


The upper lateral backrest tilt adjustment strap might start to tear during use. This tear can lead to a complete rupture of the strap. This specific strap does not affect the harness' structure but might impact the support of the pilot, making the harness uncomfortable especially if the second adjustment strap is not set properly.

This can also lead to a lack of position awareness and support of the pilot and might have consequences on certain phases of flight.

Suite page 2 ►

Published date	12/12/2018
Document number	SUPAIR_2018/12/002
Page number	2 / 2

Procedure to follow :



Person able to perform the harness :

USER

DEALER

MANUFACTURER

DELAIS : The inspection must be done immediately

Documents recipients :

USER

DEALER

SCHOOLS

CLUBS

MAGAZINES

ASSOCIATIONS

Communiqué sécurité : SUPAIR_2018/12_002