

RETROFITTING DIRECTIVE FOR FINSTERWALDER PARALOCK 3 SEPARATION CARABINERS

According to the manufacturer's instructions, all Paralock 3 separation carabiners must be retrofitted with line guards. Without this retrofit, the carabiners lose their operational approval.

The retrofit will be carried out **free of charge by the manufacturer**. Affected carabiners should be sent to the following address:

Finsterwalder GmbH, Pagodenburgstraße 8, 81247 Munich, GERMANY

Customers in Switzerland are kindly requested to send their carabiners directly to the following address:

High Adventure AG, Wiesenbergstrasse 10, 6383 Dallenwil, SWITZERLAND

All Swiss submissions will be collected and forwarded to us in batches in order to simplify the process.

Important Note: It is not possible to retrofit Paralock 1 carabiners with line guards. As an alternative, we offer the exchange of Paralock 1 carabiners for pre-equipped Paralock 3 carabiners at a price of €35 each (plus shipping).

Please ensure that the [instruction manual for the retrofitted Paralock 3](#) is carefully observed.

Munich, 22.04.2025

Finsterwalder GmbH

<https://www.fensterwalder-charly.de>

