

Date	April / 2018
Number of pages	1/3

SAFETY NOTE

Product: Harness Calliplox and Calliplox Reverse.

Problem: Rescue Lines possibility to hook on zipper puller inside of the rescue compartment.

Procedure: All harnesses SOL Paragliders Calliplox and Calliplox Reverse must be checked before next flight.



- Open the rescue compartment.



- Check if the zipper puller offers risk to hook the line or cause malfunction of the rescue use



1) If it is **OK**: following the normal rescue installing.

2) if it is **not OK** : You must use pliers to tighten the zipper puller:

3) Take the pliers and carefully try to tighten nicely to not damage the zipper.



4) Another inspection is necessary until you install your rescue inside of the compartment.



This procedure must be enough to solve the problem,
however if you still have any questions,
please contact us:



IKARUS.BE
Hammestraat 44
BE-9850 Hansbeke
+32 477 923424 info@ikarus.be www.ikarus.be